

## Marking Guide

END OF DEFECTS LIABILITY CHECKLIST	
Fictitious workplace	UP Building and Construction Pty Ltd
Date of review	01/11/2022
Reviewer's name	Student's name

### Details of the Building and Construction Project

Name of building and construction project	Granny flat	
Overview of this project	Build a granny flat in the owner's backyard.	
Project site address	15 Boronia street Springwood [Student's state]	
State/territory	[Student's state/territory]	
Checklist items:	YES/NO	Remedy
1. Timber flooring has been scratched during construction	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	Sand and replace scratched timber flooring
2. Painting has been missed in the bedroom	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	Re paint bedroom